

State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director Governor
GARY R. HERBERT
Lieutenant Governor

JON M. HUNTSMAN, JR.

Representatives Present During the Inspection:						
Company	Dennis Ware Controller					
OGM	Steve Demczak Environmental Scientist III					

Inspection Report

Permit Number:	C0070006			
Inspection Type:	PARTIAL			
Inspection Date:	Tuesday, April 22, 2008			
Start Date/Time:	4/22/2008 2:00:00 PM			
End Date/Time:	4/22/2008 4:00:00 PM			
Last Inspection:	Wednesday, March 12, 2008			

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny,60's

InspectionID Report Number: 1629

Accepted by: jhelfric

4/30/2008

Permitee: PLATEAU MINING CORP
Operator: PLATEAU MINING CORP

Site: STAR POINT MINE

Address: PO BOX 30, HELPER UT 84526-0030

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages

8,919.91	Total Permitted		
113.34	Total Disturbed		
113.34	Phase I		
	Phase II		
	Phase III		

Mineral Ownership

Federal

State

Other

County

Types of Operations

✓ Underground

Surface
Loadout

☐ Processing
☐ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Steve Demczak, Environmental Scientist III

Date

Tuesday, April 29, 2008

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070006 Inspection Type: PARTIAL

Inspection Date: Tuesday, April 22, 2008

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers				
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	V		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	✓		V	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	✓		✓	
13.	Revegetation	V		✓	
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing	✓		✓	
16.Ł	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	✓		✓	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other		П		

Permit Number: C0070006 Inspection Type: PARTIAL

Inspection Date: Tuesday, April 22, 2008

Page 3 of 3

3. Topsoil

All topsoil was used for reclamation.

4.a Hydrologic Balance: Diversions

Diversions were spot-checked and would function during a storm event. There were no signs of water erosion.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

All sediment ponds are removed.

4.d Hydrologic Balance: Water Monitoring

The permittee submitted third quarter water data to the Division.

10. Slides and Other Damage

No slides were noticed during the inspection.

12. Backfilling And Grading

The mine site is complete backfilled and graded.

13. Revegetation

The mine site has been seeded.

16.a Roads: Construction, Maintenance, Surfacing

This road is now a County Road.

18. Support Facilities, Utility Installations

No facilities are on site.